This Page Is Inserted by IFW Operations and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):


- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- · FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.


As rescanning documents will not correct images, please do not report the images to the Image Problem Mailbox.

TOTARO BRITICADO


<u>€</u>









TOTALO OF TELLOS












Express Mail Label No. EL 890727887 US
Title APPARATUS FOR TREATING A FLOOR SURFACE
Inventor: William R. Stuchlik
File: TDCI 4347.5
Attorney: Richard L. Bridge Phone: (314) 231-5400





Express Mail Label No. EL 890727887 US Title APPARATUS FOR TREATING A FLOOR SURFACE Inventor: William R. Stuchlik File: TDCI 4347.5


Attorney: Richard L. Bridge Phone: (314) 231-5400















13/14

Express Mail Label No. EL 890727887 US
Title APPARATUS FOR TREATING A FLOOR SURFACE
Inventor: William R. Stuchlik
File: TDCI 4347.5
Attorney: Richard L. Bridge Phone: (314) 231-5400



Express Mail Label No. EL. 890727887 US
Title APPARATUS FOR TREATING A FLOOR SURFACE
Inventor: William R. Stuchlik
File: TDCI 4347.5
Attorney: Richard L. Bridge Phone: (314) 231-5400

